



Please note that in case you have version 1.3 or older versions in your DAS240, you must install first version 1.4 and only then version 2.2

Improvements / changes of version 2.2 DAS220-240

Main improvements:

- ➤ Improvement of the WiFi control
- > The update of alarms is accelerated

Minor bugs correction

Improvements / changes of version 2.1 DAS240

Main improvements:

- ➤ Multiple files selection added
- ➤ Improvement of the display for functions, complex trigger, units change

Minor bugs correction

Improvements / changes of version 2.0 DAS240

Main improvements:

- ➤ Improvement of the display of temperature measurements
- Resolution for Pt100-Pt1000 is now 0.1°C
- > Improvement of data buffer management

Minor bugs correction

Improvements / changes of version 1.7 DAS240

Main improvements:

> TCP commands added





- ➤ New WiFi driver added
- > Compatibility with LabVIEW driver

Minor bugs correction

Improvements / changes of version 1.5 DAS240

Main improvements:

- > Alarm status is added in the status bar.
- > Improvement of standard deviation calculation
- > Channel increment added in the math calculation window
- ➤ Math calculation between cursors has been added
- > Improvement of Pt100 3 wires with long integration period
- ➤ Web Services added and the download of files when recording is authorized

Minor bugs correction

This firmware update is fully compatible with **DAS240**

If you want to be informed of software releases and new products introduction, please follow-us on Twitter: @SEFRAM_SAS